



Note: Early and rebuilt models may have 3/4 NPT ports in the manifolds and therefore require fittings with pipe threads. Contact Hallco for part numbers for those fittings.

-Figure 41-  
Standard 4200 (Two-Way) Plumbing